Occasionally with a new data cartridge, medium errors may occur after only a few hours. If this occurs, perform a cleaning cycle after the first 4 to 5 hours of tape movement with the new tape. If medium errors persist, run two or more consecutive cleaning cycles. If errors still occur, the tape should be replaced.

## Proper Cartridges for DIGITAL DAT drives

Use of non-DDS marked media may result in degraded drive performance and is not recommended. Digital recommends the use of Digital Equipment Corporation media.

60m
60m, 90m
60m, 90m, 120m
60m, 90m, 120m
60m, 90m, 120m, 125m

## **Orderable Part Numbers**

60m (DDS-1)	TLZ04-CA
90m (DDS-1)	TLZ06-CA (5-pack-TLZ06-CB)
120m (DDS-2)	TLZ07-CA (5-pack-TLZ07-CB)
125m (DDS-3)	TLZ10-CA (10-pack-TLZ10-CB)
Cleaning Cartridge	TLZ04-HA

To order:

Call 1-800-DIGITAL

http://www.businesslink.digital.com

Printed in U.S.A. EK–SM2TE–RC. A01
© Digital Equipment Corporation, 1997
All Rights Reserved