



EK-AL275-DK Errata Sheet

There is an error in Figure 3-1, "Alpha PCI 64-275 Power Connectors," in the *Alpha PCI 64-275 User's Manual*, EK-AL275-UM.

The figure shows pin 1 at the right-hand end of connectors J27 and J28. Pin 1 is actually at the left-hand end of connectors J27 and J28.

Pin 1 for each connector is identified on the board with a "V" or "1" symbol.