digital

DIGITAL GIGAswitch/IP Solution for ATM

May 1997

READ ME FIRST

Dear Customer,

Thank you for buying this DIGITAL product.

The purpose of this letter is to inform you of a solution to a problem that exists with Version 1.3-D of the DIGITAL GIGAswitch/IP Switch Controller and the DIGITAL IP Switch Gateway software.

Problem: The IGRP protocol is not enabled as the default on the Version 1.3-D software.

Solution: Log in to the GIGAswitch/IP Switch Controller or IP Switch Gateway as user admin and issue the following commands at the # prompt:

cd /usr/local/config/bin
./dbset "protocol:igrp" t
./dbset save save

Complete these steps for every controller and gateway with Version 1.3-D software that you have received.

Note

If you perform an unconfig operation, you must repeat this procedure to re-enable the IGRP protocol.